Sr. No.	Ward	Beat No.	Location of wells	Water Test Report	Status of work	Whether the water is salty (by physical inspection)	Yield in litres/Hour	Whether the water tank & pump installation is feasible		Estimated cost in Rs.	Remarks
1	2	3	4	5	6	7	8	9	10	11	12
1	E	206	Mhatarpakhadi	Test result awaited	Completed	No	3500	Yes	Yes	4,68,800.00	Repair work carried at estimated cost of Rs.4,68,800/-
2	E	202	V.J.B. Udyan near S.G. Office	Test result awaited	Completed	No	4000	Already existing	Yes	6,71,800.00	Repair work carried at estimated cost of Rs.6,71,800/-
3	E	202	V.J.B. Udyan behind S.G. Office	Test result awaited	Completed	No	4000	Already existing	Yes	6,96,600.00	Repair work carried at estimated cost of Rs.6,96,600/-
4	E	202	Poddar Compound	potable	Completed	No	4000	Already existing	Yes	2,54,300.00	Repair work carried at estimated cost of Rs.2,54,300/-