

MUNICIPAL CORPORATION OF GREATER MUMBAI**Repair of wells in 'L' ward.**

| Sr. No. | Beat No. | Location of Wells | Water Test Report | Status of work | Whether the water is salty (By Visual Inspection) | Yield in Ltrs./Hour | Whether the Water Tank & Pump instalation is feasible | Whether the filtration plant is feasible | Estimated cost in Rs. | Remarks |
|---------|----------|---|---|-------------------|---|---------------------|---|--|-----------------------|---------|
| 1 | 150 | Uday Nagar,Saki Vihar Road | Water Sample is found unfit for potable purpose. | Work completed | No | 3766.67 | No | No | 243500 | |
| 2 | 150 | Khapne Chawl, Kurla(W). | Water Sample is found chemically fit for potable purpose. | Work completed | No | 1802.92 | No | No | 104300 | |
| 3 | 150 | Sukhshanti Hsg. Society,Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | Yes | 716.7 | Yes | No | 92000 | |
| 4 | 150 | Munnu Bhai Chawl, Near Musjid, Sakinaka, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | Yes | N.A. | 102100 | |
| 5 | 150 | Munnu Bhai Chawl, behind Municipal School, Sakinaka, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | No | N.A. | 117100 | |

| | | | | | | | | | | |
|----|-----|--|---|--|------|--------|------|------|--------|--|
| 6 | 151 | Rajaram Yadav Chawl | N.A. | Work not started due to public grivences | N.A. | N.A. | N.A. | N.A. | 190300 | |
| 7 | 151 | Somaiya Quarry, Sakinaka, Kurla(W) | Water Sample is found unfit for potable purpose. | Work in progress. | N.A. | N.A. | Yes | N.A. | 190300 | |
| 8 | 151 | Near Dispensary, Vijay Fair Road, Sakinaka, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | N.A. | N.A. | 100700 | |
| 9 | 151 | Sardar Compound, Sakinaka, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | N.A. | N.A. | 178700 | |
| 10 | 152 | Natekar Chawl,JMM Rd. | Water Samples are sent for testing. Test reports are awaited. | Work completed | No | 635.83 | No | No | 289750 | |
| 11 | 152 | Vishwa Hindu Parishad, Bajrang Dal, Pipeline Rd,Kurla(W) | Water Samples are sent for testing. Test reports are awaited. | Work completed | Yes | 460.5 | Yes | No | 155950 | |

| | | | | | | | | | | |
|----|-----|---|---|----------------------|------|--------|-----|------|--------|--|
| 12 | 152 | Nikam Chawl ,Subhash Nagar ,J.M.M. road, Kurla(w) | Water Samples are sent for testing. Test reports are awaited. | Work completed | No | 635.83 | Yes | No | 136600 | |
| 13 | 152 | Haranasing Chawl ,Kulkarni wadi, J.M.M. road, Kurla(w) | Water Samples are sent for testing. Test reports are awaited. | Work completed | Yes | 384.63 | No | No | 149800 | |
| 14 | 152 | Matruchhayy, chawl Datta Nagar , J.M.M. road, Kurla(w) | Water Samples are sent for testing. Test reports are awaited. | Work completed | No | 894.17 | No | No | 135250 | |
| 15 | 152 | Panser Sadan, Ganesh Mandir Marg, Asalfa, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | Yes | N.A. | 217300 | |

| | | | | | | | | | | |
|----|-----|--|--|----------------------|------|--------|------|------|--------|--|
| 16 | 152 | Bhaujinar Patel Chawl, Asalfa Pipe line Road, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | Yes | N.A. | 213350 | |
| 17 | 152 | P.V.K. Compound, Khairani Road, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | N.A. | N.A. | 227050 | |
| 18 | 153 | Patel Wadi, G.A. Link Rd. | Water Sample is found chemically fit for potable purpose. | Work completed | No | 276.25 | No | No | 289150 | |
| 19 | 153 | Shri Ramleela Mahotsav, Milind Nagar-2 | Water Sample is found chemically fit for potable purpose. | Work completed | No | 590 | Yes | No | 299450 | |
| 20 | 153 | Valmaki nagar ,Milind nagar 2, Himalaya Soc. road Kurla(w) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 827.92 | No | No | 162500 | |

| | | | | | | | | | | |
|----|-----|---|--|----------------------|-------|--------|-------|-------|--------|--|
| 21 | 153 | Ashok Chawl ,L.B.S. nagar road , Kurla(w) | ----- | ----- | ----- | ----- | ----- | ----- | 122050 | |
| 22 | 153 | Satyam Shivam Soc. , Khadi no.3 , Hanuman road , Kurla(w) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 250.83 | No | No | 146550 | |
| 23 | 153 | Bhanu Prakash Hos. Soc. , Tilak ngar ,90 ft road, Kurla(w) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 614.17 | Yes | No | 151600 | |
| 24 | 153 | Aashapura Soc. L.B.S. nagar road , Kurla(w), | Water Sample is found chemically fit for potable purpose. | Work completed | No | 197.5 | No | No | 151000 | |
| 25 | 153 | Om Soci. Ashpura, L.B.S. Baug, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | N.A. | N.A. | 141400 | |
| 26 | 154 | Ram Narayan Shiv Niwas Chawl,Kaju Pada | Water Sample is found chemically fit for potable purpose. | Work completed | No | 704.17 | Yes | yes | 322500 | |

| | | | | | | | | | | |
|----|-----|--|---|-------------------|------|--------|-----|------|--------|--|
| 27 | 154 | Trupti Sadan Chawl, 90 feet road, Kurla (W). | Water Sample is found chemically fit for potable purpose. | Work completed | No | 950 | Yes | yes | 150200 | |
| 28 | 154 | Ram Raj Yadav Chawl, Kajupada, Kurla (W). | Water Sample is found unfit for potable purpose. | Work completed | No | 614.58 | Yes | yes | 151900 | |
| 29 | 154 | Pujari Chawl, Kajupada, Kurla (W). | Water Sample is found chemically fit for potable purpose. | Work completed | No | 291.67 | No | No | 150000 | |
| 30 | 154 | Gomes Chawl, Satya Nagar, Kurla (W). | Water Samples are sent for testing. Test reports are awaited. | Work completed | N.A. | 719.58 | Yes | Yes | 151500 | |
| 31 | 154 | Jai Durga Chawl, 90 feet road, Kurla (W). | Water Samples are sent for testing. Test reports are awaited. | Work completed | N.A. | 691.67 | Yes | No | 152900 | |
| 32 | 154 | Shri Krishna Chawl, Sundar Baug, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | Yes | N.A. | 347900 | |

| | | | | | | | | | | |
|----|-----|---|---|-------------------|-----|---------|-----|----|--------|--|
| 33 | 155 | Khimji Chawl, Jarimari | Water Sample is found chemically fit for potable purpose. | Work completed | No | 2018.75 | Yes | No | 358500 | |
| 34 | 155 | Akbar Chawl, Sandesh Nagar. | Water Samples are sent for testing. Test reports are awaited. | Work completed | No | 3104.17 | No | No | 436800 | |
| 35 | 155 | Kadari chawl, Jari mari , Kurla(w), | Water Sample is found unfit for potable purpose. | Work completed | Yes | 2473.33 | Yes | No | 150600 | |
| 36 | 156 | Sunderbaug Nagar | Water Sample is found chemically fit for potable purpose. | Work completed | No | 1162.92 | Yes | No | 144300 | |
| 37 | 156 | Mahavir Jewellers , Sanjay nagar , Kurla(w), | Water Sample is found chemically fit for potable purpose. | Work completed | No | 705.83 | Yes | No | 170000 | |

| | | | | | | | | | | |
|----|-----|---|--|---|-----|---------|-----|-----|--------|--|
| 38 | 156 | lalmal chawl ,Hanuman mandir , Sundar bang , Kurla(w), | Water Sample is found chemically fit for potable purpose. | Work completed | No | 782.92 | Yes | No | 142200 | |
| 39 | 157 | Wadeshwar Mitra Mandal,Turdew adi | Water Sample is found unfit for potable purpose. | Work completed | Yes | 736.25 | Yes | No | 288500 | |
| 40 | 157 | Santaram Baug , opp. Shital talkies , L.B.S. marg , Kurla(w), | N.A. | Work not started due to public grivences | No | 0 | | | 160000 | |
| 41 | 157 | Shingare wadi ,Kale Marg Kurla(w) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 782.92 | Yes | No | Nil | Work was completed in year 2007-2008 |
| 42 | 157 | Ghulkar wadi,M.N. road Kurla(w) | Water Sample is found unfit for potable purpose. | Work completed | No | 830 | Yes | No | 183800 | |
| 43 | 157 | Almeda baug,Sheetal talav Kurla(w) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 2791.67 | Yes | Yes | Nil | Work was completed in year 2007-2008 |

| | | | | | | | | | | |
|----|-----|--|--|----------------------|------|---------|------|------|--------|--|
| 44 | 157 | Barve Chawl Kale Marg | Water Sample is found chemically fit for potable purpose. | Work completed | No | 1731.25 | Yes | No | 128800 | |
| 45 | 157 | Anand Bhavan ,K.A.road Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | No | 783.75 | Yes | No | 291900 | |
| 46 | 157 | Navapad Kurla(W) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 1058.75 | Yes | Yes | 438000 | |
| 47 | 157 | Akansha Society M.N. road Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | No | 833.33 | Yes | No | 160100 | |
| 48 | 157 | Bhoiwadi, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | N.A. | N.A. | 195700 | |
| 49 | 158 | Ramdas Chowk | Water Samples were sent for testing. Test reports are awaited. | Work completed | No | 759.58 | Yes | No | 161400 | |

| | | | | | | | | | | |
|----|-----|-------------------------------------|--|-------------------|------|---------|-----|------|--------|--|
| 50 | 158 | Sambhaji Chowk, N.M. Road,Kurla(W) | Water Samples were sent for testing. Test reports are awaited. | Work completed | No | 966.67 | Yes | No | 172500 | |
| 51 | 159 | Gazibaba Dargah& Vishwakarma Mandal | Water Samples were sent for testing. Test reports are awaited. | Work completed | No | 337.5 | Yes | No | 178200 | |
| 52 | 159 | Gauri Shankar Mandir, Kurla(W) | Water Samples were sent for testing. Test reports are awaited. | Work completed | No | 205.83 | Yes | No | 128800 | |
| 53 | 161 | Hira Kumbhar Chawl, Kurla(W) | Water Samples were sent for testing. Test reports are awaited. | Work completed | No | 2620 | Yes | Yes | 167300 | |
| 54 | 161 | Near Subhash Nagar, Kurla(W) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | Yes | N.A. | 225300 | |
| 55 | 162 | Dugad Chawl, Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | No | 2313.75 | Yes | Yes | 438000 | |

| | | | | | | | | | | |
|----|-----|------------------------------------|---|----------------|----|--------|-----|----|--------|--|
| 56 | 162 | Maharashtra Vyayam Shala, Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | No | 318.33 | Yes | No | 160100 | |
| 57 | 162 | Jama Masjid, Kurla(W) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 314.17 | No | No | 161400 | |
| 58 | 162 | Takiya Ward Market, Kurla(W) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 1135 | Yes | No | 172500 | |
| 59 | 162 | Abdullah Mansion, Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | No | 553.67 | Yes | No | 178200 | |
| 60 | 162 | Vijay Mansion, Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | No | 792.5 | Yes | No | 158600 | |
| 61 | 162 | Koyanabai Chawl, Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | No | 312.5 | Yes | No | 167300 | |

| | | | | | | | | | | |
|----|-----|---|--|----------------------|------|---------|-----|------|--------|--|
| 62 | 162 | Gol Building, Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | Yes | 194.17 | No | No | 161300 | |
| 63 | 162 | Chiknebai Chawl,Kurla(W) | Water Sample is found unfit for potable purpose. | Work completed | No | 666.67 | No | No | 160400 | |
| 64 | 163 | Haji Naamdar Chawl, Kurla(E) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 362.5 | Yes | No | 448550 | |
| 65 | 164 | Gorakshnath Mandal, S.M. Road, Kurla(E) | Water Sample is found chemically fit for potable purpose. | Work completed | No | 1404.16 | Yes | No | 239850 | |
| 66 | 164 | Dhobi Ghat, MuktaDevi Rd | Water Sample is found chemically fit for potable purpose. | Work completed | No | 192.5 | No | No | 227750 | |
| 67 | 164 | Muktadevi Road, Infront of Datta Mandir, Chunabhatti, Kurla(E) | Water samples are not sent for testing. | Work in progress. | N.A. | N.A. | Yes | N.A. | 148700 | |

[illegible]