

MUNICIPAL CORPORATION OF GREATER MUMBAI

REPORT FOR REPAIRS / DESLUDGING OF WELLS IN R/NORTH WARD

Sr. No.	Ward	Beat No.	Location of Wells	Water Test Report	Status of Work	Whether the water is salty (by physical inspection)	Yield in ltrs. / hr.	Whether the water Tank & pump installation is feasible	Whether the water filtration plant is feasible	Estimated amount in (Rs.)	Remarks
1	R/ North	2	Thakur House, Moreshwar Patil road, Dahisar (West)	Unfit for potable purposes	Work Completed	No smell, clear water with a few brown & white particle	700	Not feasible	Not feasible	198200/	Work Completed
2	R/ North	2	Salunke House, Near Joshi Apt., Thomas D'silva Rd, Dahisar(West)	Unfit for potable purposes	Work Completed	No smell, clear water with a few brown & white particle	400	Not feasible	Not feasible	198200/	Work Completed
3	R/ North	3	Ramchandra Gurav chawl, Ketakipada, Dahisar(East)	Chemically fit for potable purposes	Work Completed	No smell, clear water with a few brown & white particles	400	Not feasible	Not feasible	8,46,500	Work Completed
4	R/ North	3	Tulja Bhavani Chawl, Shivaji nagar,ketakipada, Dahisar (East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/ North	500	Not feasible	Not feasible		Work Completed
5	R/ North	3	Ketki Body, KetakipadaDahisar(East)	Unfit for potable purposes	Work Completed	No smell, clear water with a many brown & white particles	2800	Not feasible	Not feasible		Work Completed
6	R/ North	3	Dahibhavkar compound, siddhivinayak Chawl, Dahisar (east)	Chemically fit for potable purposes	Work Completed & Prop - Pumping arrangement	No smell, clear water with a few brown & white particles	3200	Feasible	Not feasible		Work Completed & Prop - Pumping arrangement
7	R/ North	3	Jhillu Mistry chawl ,Adarsh Welfare So. Near Namdev chawl, Dahisar (East)	Unfit for potable purposes	Work Completed & Prop - Pumping arrangement	No smell, clear water with a few brown & white particles	500	feasible	Not feasible		Work Completed & Prop - Pumping arrangement
8	R/ North	3	Lokhande Chawl, Ketakipada Dahisar (East)	Unfit for potable purposes	Work Completed	Earthy smell, turbid water with a few brown & white particles	200	Not feasible	Not feasible		Work Completed
9	R/ North	3	Ramnagar, Dharkhadi, Dahisar (east)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	350	Not feasible	Not feasible		Work Completed

Sr. No.	Ward	Beat No.	Location of Wells	Water Test Report	Status of Work	Whether the water is salty (by physical Inspection)	Yield in ltrs. / hr.	Whether the water Tank & pump installation is feasible	Whether the water filtration plant is feasible	Estimated amount in (Rs.)	Remarks
10	R/ North	3	Shyam Rathi Chawl, Dahisar (East)	Chemically fit for potable purposes	Work Completed	No smell, clear water with a few brown & white particles	1200	Not feasible	Not feasible	640240/	Work Completed
11	R/ North	3	Kaji Yadav Chawl, Dahisar (East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	950	Not feasible	Not feasible		Work Completed
12	R/ North	3	Shanti nagar, near mahadev mandir, Dahisar (East)	Report is awaited from M.O.H. R/North	Work Completed & Prop - Pumping arrangement	Report is awaited from M.O.H.R/North	3000	feasible	Not feasible		Work Completed & Prop - Pumping arrangement
13	R/ North	3	B.G. Kadam Chawl, Dahisar (East)	Chemically fit for potable purposes	Work Completed	No smell, clear water with a few brown & white particles	900	Not feasible	Not feasible		Work Completed
14	R/ North	4	Dyaneshwar nagar, Jivdani Welfare Society, Dahisatr (east)	Report is awaited from M.O.H. R/North	Work Completed & Prop - Pumping arrangement	Report is awaited from M.O.H.R/North	2700	feasible	Not feasible	403100/	Work Completed & Prop - Pumping arrangement
15	R/ North	4	Gokul Nagar, Dahisar (East)	Report is awaited from M.O.H. R/North	Work Completed & Prop - Pumping arrangement	Report is awaited from M.O.H.R/North	3700	feasible	Not feasible		Work Completed & Prop - Pumping arrangement

Sr. No.	Ward	Beat No.	Location of Wells	Water Test Report	Status of Work	Whether the water is salty (by physical inspection)	Yield in ltrs. / hr.	Whether the water Tank & pump installation is feasible	Whether the water filtration plant is feasible	Estimated amount in (Rs.)	Remarks
16	R/ North	4	Suyog nagar, Ghartanpada no 2, Dube Chawl, Dahisar (East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	2280	Not feasible	Not feasible	564400/	Work Completed
17	R/ North	4	Fulwati devi mathur Chawl, Dahisar (East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	2690	Not feasible	Not feasible		Work Completed
18	R/ North	4	Keshav Nagar, Dahisar(East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	715	Not feasible	Not feasible		Work Completed
19	R/ North	4	Tumade nagar, siddhivinayak Chawl, Dahisar (east)	Unfit for potable purposes	Work Completed & Prop - Pumping arrangement	No smell, clear water with few brown & white particles	6000	feasible	Not feasible		Work Completed & Prop - Pumping arrangement
20	R/ North	5	Ramrup Yadav Chawl,balkawade compound, Hanuman tekadi Dahisar(East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	2263	Not feasible	Not feasible	799360/	Work Completed
21	R/ North	5	Rangbahadar Chawl, Sambhaji Nagar, Dahisar(East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	2512	Not feasible	Not feasible		Work Completed
22	R/ North	5	Suthar Chawl, Murbadi Talao, Dahisar(East)	Unfit for potable purposes	Work Completed & Prop - Pumping arrangement	No smell, clear water with a few brown & white particle	3500	feasible	Not feasible		Work Completed & Prop - Pumping arrangement
23	R/ North	5	Desai Wadi Chawl, Dahisar (East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	1500	Not feasible	Not feasible		Work Completed

Sr. No.	Ward	Beat No.	Location of Wells	Water Test Report	Status of Work	Whether the water is salty (by physical Inspection)	Yield in ltrs. / hr.	Whether the water Tank & pump installation is feasible	Whether the water filtration plant is feasible	Estimated amount in (Rs.)	Remarks
24	R/ North	5	Near Maruti mall, Sambhaji Nagar, Dahisar (East)	Unfit for potable purposes	Work Completed & Prop - Pumping arrangement	No smell, clear water with a few brown & white particle	3600	feasible	Not feasible	710080/	Work Completed & Prop - Pumping arrangement
25	R/ North	5	Sant Dnyaneshwar Nagar, Savarpada, nr booster pump Dahisar (East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	4200	Not feasible	Not feasible		Work Completed
26	R/ North	5	Sankalp Siddhi, Babu Petekar Chawl, Savarpada, Dahisar (East)	Chemically fit for potable purposes	Work Completed & Prop - Pumping arrangement	No smell, clear water with few brown & white particles	3400	feasible	Not feasible		Work Completed & Prop - Pumping arrangement
27	R/ North	5	Nr. Gautam Jadhav Home, Ganesh Nagar, Dahisar (E)	Report is awaited from M.O.H. R/North	Work Completed	No smell, clear water with a few brown & white particle	3900	Not feasible	Not feasible		Work Completed
28	R/ North	5	Shanti Niwas Seva Samiti, Dahisar (E)	Unfit for potable purposes	Work Completed & Prop - Pumping arrangement	No smell, clear water with a few brown & white particle	3900	feasible	Not feasible	348600/	Work Completed & Prop - Pumping arrangement
29	R/ North	5	Back Side of Barot Saree Centre, Ganesh nagar, D/E	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H.R/North	4250	Not feasible	Not feasible		Work Completed

Sr. No.	Ward	Beat No.	Location of Wells	Water Test Report	Status of Work	Whether the water is salty (by physical Inspection)	Yield in ltrs. / hr.	Whether the water Tank & pump installation is feasible	Whether the water filtration plant is feasible	Estimated amount in (Rs.)	Remarks
30	R/ North	6	Pirani compound, Ambewadi, S.V. road Dahisar (East)	Unfit for potable purposes	Work Completed & Pumping arrangement	No smell, clear water with a few brown & white particle	2500	feasible	Not feasible	686700/	Work Completed & Pumping arrangement
31	R/ North	6	Khot Chawl, S.V. Road , Dahisar (East)	Unfit for potable purposes	Work Completed & Pumping arrangement	No smell, clear water with a few brown & white particle	625	feasible	Not feasible		Work Completed & Pumping arrangement
32	R/ North	6	M.C. Compound, Ambawadi, Dahisar (East)	Report is awaited from M.O.H. R/North	Work Completed	Report is awaited from M.O.H. R/North	250	Not feasible	Not feasible		Work Completed
33	R/ North	6	Khot Wadi, Mathura Bldg., Overipada, Dahisar (E)	Chemically fit for potable purposes	Work Completed & Pumping arrangement	No smell, clear water with a few brown & white particle	2290	Feasible	Not feasible		Work Completed & Pumping arrangement
34	R/ North	6	Overipada Garden, Aakash Krida Mandal, Dahisar (E).	Unfit for potable purposes	Work Completed	No smell, clear water with a few brown & white particle	2500	Not feasible	Not feasible		Work Completed & Pumping arrangement
35	R/ North	7	Gupta Chawl, Shivaji Nagar, Dahisar (W)	Unfit for potable purposes	Work Completed	Sewage smell, Turbid water with many brown & white particles	610	Not feasible	Not feasible	612533/	Work Completed
36	R/ North	7	Opp. Shreeji Complex, Shivaji Nagar, Dahisar (W).	Unfit for potable purposes	Work Completed	No smell, clear water with a few brown & white particle	940	Not feasible	Not feasible		Work Completed
37	R/ North	7	Opp. Mandpeshwar Caves, Shivaji Nagar, Dahisar (W).	Chemically fit for potable purposes	Work Completed & Prop - Pumping arrangement	No smell, Earthy water with few brown & white particles	1000	feasible	Not feasible		Work Completed & Prop - Pumping arrangement
38	R/ North	7	Pragati Mandal, Shivaji Nagar, Dahisar (W).	Chemically fit for potable purposes	Work Completed	No smell, Earthy water with few brown & white particles	260	Not feasible	Not feasible		Work Completed

Sd/-
6.3.2010

A.C. R/North Ward